
Abandoned Vessel Inventory

Vessel List :VI
April 08, 2004

Name	Priority	Description	Location	Primary Source
------	----------	-------------	----------	----------------

USVI

AMALIE QUEEN	Low	Grounded 1989; 49' ferry Ferry grounded partly in a salt pond with a lagoon behind it.	N: 18.3197 W: 64.94 Land use: Recreational, there are a lot of boats and trash along the shore.	USCG - VCAS
--------------	-----	---	--	-------------

USVI - St. Croix

Unknown2440	Low	Grounded; 67' cargo/supply An ex US Navy supply boat grounded and deteriorating.	N: 17.6844 W: 64.7627 The land surrounding the bay is owned by the USVI and is a DPNR wildlife preserve.	AVP
-------------	-----	---	---	-----

USVI - St. Croix, Altoona L.

Devcon Dredge	Medium	Derelict; 60' barge potential nav. hazard	PA	AVIS
Judtih Fancy	Medium	Derelict; 40' barge	PA	AVIS
Unknown1868	Medium	Derelict; 30' barge no identifying marks	PA	AVIS

USVI - St. Croix, Christiansted Hbr

Abandoned Vessel Inventory

Vessel List :VI
April 08, 2004

Name	Priority	Description	Location	Primary Source
------	----------	-------------	----------	----------------

USVI - St. Croix, Christiansted Hbr

Unknown2435	Medium	Sunk 1989; 28' sailboat The vessel sank on its mooring during Hurricane Hugo in 1989.	N: 17.7481 W: 64.7059 - Christiansted Harbor is a heavily used mooring area. The land surrounding the harbor is territorially owned and is mostly	AVP
Unknown2436	Low	Sunk 1989; 28' sailboat - catamaran Fiberglass catamaran, 28 ft, buried with one pontoon showing, mostly in pieces.	N: 17.7481 W: 64.7225 Christiansted Harbor is a heavily used mooring area. The land surrounding the harbor is territorially owned and is mostly	AVP
Unknown2437	Low	Grounded; barge Steel barge ashore adjacent to St. Croix marina.	N: 17.7494 W: 64.6974 Christiansted Harbor is a heavily used mooring area. The land surrounding the harbor is territorially owned and is mostly	AVP
Unknown2438	Low	Grounded; dredge Steel dredge/barge ashore near entrance to Altona Lagoon.	N: 17.7497 W: 64.6968 Christiansted Harbor is a heavily used mooring area. The land surrounding the harbor is territorially owned and is mostly	AVP

USVI - St. Croix, Gallows Bay

Unknown2439	Low	Grounded; sailboat Burned sailboat on wheeled device for hauling out of water.	N: 17.7458 W: 64.7 The land surrounding the bay is territorially owned and mostly used by privately owned businesses and marinas.	AVP
-------------	-----	---	--	-----

USVI - St. Croix, Krause L.

Abandoned Vessel Inventory

Vessel List :VI
April 08, 2004

Name	Priority	Description	Location	Primary Source
------	----------	-------------	----------	----------------

USVI - St. Croix, Krause L.

Unknown2441	Medium	Sunk 1999; 56' sailboat Sailboat sunk at mooring, possibly by Hurricane Lenny.	N: 17.7050 W: 64.7685 VIALCO, a private company, owns the adjacent land. Very sheltered mangrove cove.	AVP
-------------	--------	---	--	-----

USVI - St. Croix, Port Alucroix

Unknown1936	Medium	Derelict;	Alucroix Channel	USVI DFW
-------------	--------	-----------	------------------	----------

USVI - St. Croix, Salt R.

Bacardi	Medium	Grounded 1998; 47' sailboat Sailboat partially in the mangroves.	N: 17.7734 W: 64.7579 - The site is part of the Salt River Bay National Historic Park and Ecological Preserve, managed by the National Park Service. The site is also	AVP
Dauntless	Medium	Grounded 1998; 66' cabin cruiser Large power cruiser aground on gravel beach in mangroves.	N: 17.7715 W: 64.7999 The land surrounding the bay is part of the Salt River Bay National Historic Park and Ecological Preserve, managed by the National Park Service.	USVI DFW
Gandalf	Medium	Wreck; (recreational) Grounded in sheltered bay on east side of the Salt River.	N: 17.7786 W: 64.7506	AVP

Abandoned Vessel Inventory

Vessel List :VI
April 08, 2004

Name	Priority	Description	Location	Primary Source
<i>USVI - St. Croix, Salt R.</i>				
Kittiwake	High	Grounded 1998; 48' sailboat Sailboat grounded in very good condition.	N: 17.7720 W: 64.7585 - The site is part of the Salt River Bay National Historic Park and Ecological Preserve, managed by the National Park Service. The site is also	USVI DFW
La Gloria II	Medium	Grounded 1998; 35' fishing boat Vessel sunk on mooring in 3-6 feet of water in the middle of mooring area. Vessel is partially buoyant and could move in a storm.	N: 17.7722 W: 64.7592 The site is part of the Salt River Bay National Historic Park and Ecological Preserve, managed by the National Park Service. The site is also designated as a	USVI DFW
Mi Sueno	Medium	Grounded 1998; 26' sailboat Aground in intertidal area with sten ashore. Tied into mangroves.	The site is part of the Salt River Bay National Historic Park and Ecological Preserve, managed by the National Park Service. The site is also designated as a	USVI DFW
Unknown1940	Medium	Grounded 1998; 32' barge Small catamaran barge that grounded in a hurricane.	N: 17.7730 W: 64.7602 The site is part of the Salt River Bay National Historic Park and Ecological Preserve, managed by the National Park Service. The site is also designated as a	USVI DFW
Unknown1943	Medium	Sunk 1998; 36'	N: 17.7725 W: 64.7601 The site is part of the Salt River Bay National Historic Park and Ecological Preserve, managed by the National Park Service. The site is also designated as a	USVI DFW
Unknown1944	Medium	Sunk 1998;		USVI DFW

Abandoned Vessel Inventory

Vessel List :VI
April 08, 2004

Name	Priority	Description	Location	Primary Source
<i>USVI - St. Croix, Salt R.</i>				
Unknown1945	Medium	Sunk 1998;		USVI DFW
Unknown1946	Medium	Sunk 1998;		USVI DFW
Unknown1947	Medium	Sunk 1998;		USVI DFW
Unknown1948	Medium	Sunk 1998;		USVI DFW
Unknown2425	Low	Ground and Sink; (recreational) Pleasure craft partially sunk and grounded in the Salt River Estuary.	N: 17.771 W: 64.8 - used the coordinates from Dauntless because from the photos it is obvious that the two vessels are in close proximity	AVP
Unknown2426	Low	Wreck; (recreational) Recreational vessel ashore in an area of dead mangroves.	N: 17.771 W: 64.8 - PApprox: position of Dauntless is used. From the photos it is clear that 2426 is within site of 2425 which is within site of Dauntless	AVP

Abandoned Vessel Inventory

Vessel List :VI
April 08, 2004

Name	Priority	Description	Location	Primary Source
------	----------	-------------	----------	----------------

USVI - St. Croix, Salt R.

Unknown2427	Medium	Wreck; sailboat Ashore on gravel beach.	N: 17.77 W: 64.8 - PA - used dauntless again - just to have a rough point in the Salt River Estuary	AVP
-------------	--------	--	--	-----

Unknown2429	Low	39' sailboat - trimaran Trimaran completely in the uplands.	N: 17.7770 W: 64.7514 Upland scrub habitat	AVP
-------------	-----	--	---	-----

Unknown2430	Low	Derelict; 49' sailboat - catamaran Catamaran in the uplands.	N: 17.7769 W: 64.7516 The vessel is ashore in upland and mangrove habitat.	AVP
-------------	-----	---	--	-----

Unknown2431	Medium	Grounded; barge Barge near the entrance to the Salt River Estuary.	N: 17.7823 W: 64.7516 - Whitehorse Reef - near Salt River Lagoon entrance - about 100m offshore	AVP
-------------	--------	--	--	-----

USVI - St. Croix, Tague B.

Aleria	Medium	Grounded 1998; 20' sailboat Small fiberglass sailboat on gravel beach.	N: 17.7549 W: 64.6036 The land surrounding Tague Bay is partially public beach with private residential ownership. The submerged lands are owned by the territory	AVP
--------	--------	--	--	-----

Hobo	Medium	1998; sailboat Beached fiberglass sailboat in good condition.	N: 17.7554 W: 64.6062 The land surrounding Tague Bay is partially public beach with private residential ownership. The submerged lands are owned by the territory	AVP
------	--------	---	--	-----

Abandoned Vessel Inventory

Vessel List :VI
April 08, 2004

Name	Priority	Description	Location	Primary Source
------	----------	-------------	----------	----------------

USVI - St. Croix, Tague B.

Unknown1949	Medium	Grounded 1995; 50' sailboat	N: 17.7563 W: 64.6052	USVI DFW
-------------	--------	-----------------------------	-----------------------	----------

Unknown2434	Medium	Grounded; 20' skiff / tender Inverted fiberglass motorboat, 18-20 ft.	N: 17.7549 W: 64.6036 - Gravel beach adjacent to seagrass - The land surrounding Tague Bay is partially public beach with private residential	AVP
-------------	--------	--	--	-----

USVI - St. Thomas, Benner Bay

Benner Bay 1	Medium	Derelict; multiple derelicts?	N: 18.32 W: 64.87	individual
--------------	--------	----------------------------------	-------------------	------------

Benner Bay 2	Medium	Derelict;	N: 18.32 W: 64.87	individual
--------------	--------	-----------	-------------------	------------

Benner Houseboat 1	Medium	Derelict; houseboat are there 3-4 houseboats?	N: 18.32 W: 64.88 N side of Bovini Cay in Benner Bay Lagoon; adjacent to protected marine habitat	individual
-----------------------	--------	--	--	------------

Benner Houseboat 2	Medium	Derelict; houseboat	N: 18.32 W: 64.88	individual
-----------------------	--------	---------------------	-------------------	------------

Abandoned Vessel Inventory

Vessel List :VI
April 08, 2004

Name	Priority	Description	Location	Primary Source
<i>USVI - St. Thomas, Benner Bay</i>				
Benner Houseboat 3	Medium	Derelict; houseboat	N: 18.32 W: 64.88	individual
Emit	Medium	Grounded; sailboat Fiberglass sailboat, aground in Benner Bay.	N: 18.3167 W: 64.8665 Benner Bay is a large marina and mooring area owned by the USVI territory. - bottom is probably mud with some seagrass - although no	AVP
Franc??	Low	Grounded; sailboat Large fiberglass sailboat from Key West grounded in Benner Bay.	N: 18.3179 W: 64.8664 Benner Bay is a large marina and mooring area owned by the USVI territory.	AVP
Parasailing Platform	Low	Derelict; other	N: 18.32 W: 64.87	individual
Unknown2449	Low	Grounded 2000; 36' sailboat Fiberglass sailboat that grounded while motoring at night in 2000.	N: 18.3079 W: 64.8624 - beached on a rocky shore - potentially coral and/or hardbottom nearby - relatively high energy area	AVP
Unknown2451	Low	Grounded; sailboat Completely rusted out sailboat hull.	N: 18.3179 W: 64.8664 Benner Bay is a large marina and mooring area owned by the USVI territory.	AVP

Abandoned Vessel Inventory

Vessel List :VI
April 08, 2004

Name	Priority	Description	Location	Primary Source
<i>USVI - St. Thomas, Benner Bay</i>				
Unknown2452	Low	Grounded; sailboat Wooden sailboat grounded and rotting.	N: 18.3179 W: 64.8664 Benner Bay is a large marina and mooring area owned by the USVI territory.	AVP
Unknown2453	High	Derelict; sailboat Refloated fiberglass sailboat.	N: 18.3179 W: 64.8664 - Benner Bay is a large marina and mooring area owned by the USVI territory. - Probably mud with some seagrass	AVP
Unknown2455	Low	Grounded; sailboat Fiberglass sailboat grounded in the mangroves.	N: 18.3173 W: 64.8665 Benner Bay is a large marina and mooring area owned by the USVI territory.	AVP
Unknown2456	Low	Grounded; sailboat Inverted fiberglass sailboat hull aground with boats on top of it.	N: 18.3173 W: 64.8665	AVP
Unknown2457	Medium	Grounded; sailboat Fiberglass sailboat with holes in the hull, backed into the mangroves.	N: 18.3173 W: 64.8665	AVP
Unknown2459	Low	Grounded; power boat Damaged powerboat grounded in the mangroves.	N: 18.3184 W: 64.872 Benner Bay is a large marina and mooring area owned by the USVI territory.	AVP

Abandoned Vessel Inventory

Vessel List :VI
April 08, 2004

Name	Priority	Description	Location	Primary Source
<i>USVI - St. Thomas, Benner Bay</i>				
Unknown2460	Medium	Grounded; dive Grounded and derelict dive boat.	N: 18.3188 W: 64.8887 Benner Bay is a large marina and mooring area owned by the USVI territory.	AVP
Unknown2461	Medium	Sunk; undetermined Unidentified vessel sunk just below surface.	N: 18.3174 W: 64.8727	AVP
Unknown2462	Medium	Grounded; power boat Badly damaged fiberglass powerboat grounded in close proximity to other vessels.	N: 18.3177 W: 64.8729 Benner Bay is a large marina and mooring area owned by the USVI territory.	AVP
Unknown2463	Medium	Grounded; skiff / tender Wooden skiff in the mangroves of Benner Bay. The trees have actually started to grow through the boat.	N: 18.3177 W: 64.8729 - Benner Bay is a large marina and mooring area owned by the USVI territory.	AVP
Unknown2464	Low	Grounded; undetermined Unclassified fiberglass hull partially submerged in the mangroves.	N: 18.3171 W: 64.8735 Benner Bay is a large marina and mooring area owned by the USVI territory.	AVP
Unknown2465	Medium	Grounded; houseboat Houseboat grounded and falling apart in the mangroves.	N: 18.3166 W: 64.8732 Benner Bay is a large marina and mooring area owned by the USVI territory.	AVP

Abandoned Vessel Inventory

Vessel List :VI
April 08, 2004

Name	Priority	Description	Location	Primary Source
<i>USVI - St. Thomas, Benner Bay</i>				
Unknown2466	Low	Grounded; houseboat Hull of a houseboat grounded in the mangroves.	N: 18.3166 W: 64.8733 Benner Bay is a large marina and mooring area owned by the USVI territory.	AVP
Unknown2467	Medium	Grounded; fishing Wooden fishing vessel grounded in the mangroves.	N: 18.3168 W: 64.874 Benner Bay is a large marina and mooring area owned by the USVI territory.	AVP
Unknown2468	Medium	Ground and Sink; power boat Fiberglass powerboat that is mostly sunken.	N: 18.3168 W: 64.874 Benner Bay is a large marina and mooring area owned by the USVI territory. - There is probably seagrass in the vicinity.	AVP
Unknown2469	Medium	Sunk; pilot Large sunken powerboat.	N: 18.3168 W: 64.874 Benner Bay is a large marina and mooring area owned by the USVI territory. - Seagrass likely in the area.	AVP
Unknown2470	Low	Grounded; power boat Powerboat sunk at the edge of the mangroves.	N: 18.3169 W: 64.8738 - Seagrass likely in the area. - Benner Bay is a large marina and mooring area owned by the USVI territory.	AVP
Unknown2471	Medium	Sunk; undetermined Sunken vessel of unknown type.	N: 18.3171 W: 64.869 Benner Bay is a large marina and mooring area owned by the USVI territory. - Likely macroalgae and seagrass in vicinity.	AVP

Abandoned Vessel Inventory

Vessel List :VI
April 08, 2004

Name	Priority	Description	Location	Primary Source
<i>USVI - St. Thomas, Benner Bay</i>				
Unknown2472	Medium	Ground and Sink; barge Homemade steel workbarge that grounded and sunk.	N: 18.3165 W: 64.8694 - Mangroves, macroalgae and seagrass in vicinity. - Benner Bay is a large marina and mooring area owned by the USVI territory.	AVP
Unknown2473	Low	Derelict; sailboat Refloated fiberglass sailboat moored in apparently poor condition.	N: 18.3181 W: 64.8679 - seagrass and macroalgae in vicinity. Bay surrounded by mangroves.	AVP
Unknown2474	Medium	Derelict; undetermined Very poor condition fiberglass hull afloat in Benner bay with a small fiberglass tender stored upside down in it.	N: 18.3198 W: 64.8674 - Benner Bay is a large marina and mooring area owned by the USVI territory. - Macroalgae and seagrass also in the vicinity.	AVP
Unknown2475	Medium	Derelict; undetermined Hull with large hole upright and tied to pier.	N: 18.3198 W: 64.8674 - Benner Bay is a large marina and mooring area owned by the USVI territory. - mangroves, seagrass and macroalgae in vicinity.	AVP
Unknown2476	Medium	Derelict; undetermined Inverted small vessel mostly submerged in marina.	N: 18.3198 W: 64.8674 - Benner Bay is a large marina and mooring area owned by the USVI territory. - mangrove, seagrass and macroalgae in vicinity.	AVP
Unknown2477	Low	Derelict; fishing Fishing vessel in poor condition but still afloat.	N: 18.3198 W: 64.8674 - Benner Bay is a large marina and mooring area owned by the USVI territory. - Seagrass, mangroves and macroalgae in vicinity.	AVP

USVI - St. Thomas, Bovoni Cay

Abandoned Vessel Inventory

Vessel List :VI
April 08, 2004

Name	Priority	Description	Location	Primary Source
------	----------	-------------	----------	----------------

USVI - St. Thomas, Bovoni Cay

Unknown2450	Medium	Grounded 2002; 36' sailboat Sailboat blown off its mooring an up onto mangroves. Someone may have been in the process of righting the vessel at time of survey.	N: 18.3185 W: 64.8681 - too shallow for survey crew to get up to vessel. - likely to be seagrass habitat in their estimation.	AVP
-------------	--------	--	---	-----

USVI - St. Thomas, Careening C.

Unknown573	Medium	Grounded; 34' sailboat in 2 meters; small engines still attached?	N: 18.3297 W: 64.9347 Hassel Island is National Park Service owned, but residential area near vessel grounding pre-dates park.	AWOIS
------------	--------	--	--	-------

USVI - St. Thomas, Current Hole

Serendipity	High	Derelict 2001; 45' sailboat Serendipity has been derelict since Hurricane Lenny. The vessel is grounded in DPNR's St. James Marine Reserve and Wildlife Sanctuary.	N: 18.3153 W: 64.8337 by Current Hole Rock - grounded on DPNR St. James Marine Reserve and Wildlife Sanctuary. - Rock platform	AVP
-------------	------	---	---	-----

USVI - St. Thomas, Elephant B.

Geisha	Medium	Sunk 1995; 39' sailboat Sailboat probably sunk in Hurricane Marilyn. Submerged in mooring area but not close to channel.	N: 18.3249 W: 64.951 Adjacent land ownership: USVI territorial land with some residential property.	AVP
Unknown2442	Low	Sunk; 68' sailboat Large wood sailboat sunk and starting to deteriorate.	N: 18.3220 W: 64.9553 - Public beach, residential. - USVI territorial land with some private residential property. - The site is fairly sheltered	AVP

Abandoned Vessel Inventory

Vessel List :VI
April 08, 2004

Name	Priority	Description	Location	Primary Source
------	----------	-------------	----------	----------------

USVI - St. Thomas, Elephant B.

Unknown2443	Medium	Sunk 1983; 66' sailboat Sailboat burned and sunk on mooring in the ea rly 1980's.	N: 18.3227 W: 64.9536 - USVI territorial land with some private residential property. - Public beach, residential. - The site is fairly sheltered	AVP
Unknown2445	Medium	Ground and Sink 1975; 39' sailboat Rusted out hull of a steel sailboat that grounded and sunk in the late 1970's.	N: 18.3261 W: 64.9503 - sheltered normally but not for hurricanes - just off a public beach - in a mooring area - sand bottom and seagrass 15'	AVP
Unknown2446	Low	Ground and Sink; 105' barge Crane or dredge barge grounded and sunk in Elephant Bay.	N: 18.3271 W: 64.9501 - recreational fishing area - hard bottom and seagrass are both nearby	AVP
Unknown2447	Low	Sunk; 66' tug Tug or workboat that sunk in 9' of water.	N: 18.3271 W: 64.9501 - nearby seagrass and hardbottom	AVP
Unknown546	Medium	numerous wrecks and hulks in various conditions	N: 18.3231 W: 64.9522	AWOIS

USVI - St. Thomas, Hassel I.

Rendezvous	Medium	Derelict 1995; 75' sailboat - trimaran Large trimaran. Salvage was attempted but failed.	N: 18.3299 W: 64.9347 - National Park Service owns Hassel Island, but there are residential areas near the vessel that pre-date the park.	AVP
------------	--------	---	--	-----

Abandoned Vessel Inventory

Vessel List :VI
April 08, 2004

Name	Priority	Description	Location	Primary Source
------	----------	-------------	----------	----------------

USVI - St. Thomas, Hassel I.

Unknown2448	Medium	Grounded; 56' lifeboat Grounded lifeboat on Hassel Island that has been abandoned for a long time.	N: 18.3299 W: 64.9347 - National PS owns island but there are residential areas near vessel - Area is used as a workshop area for boats	AVP
Unknown320	Medium	Grounded 1995; 82' sailboat Large sailboat grounded on Hassel Island immediately adjacent to small building and seawall.	N: 18.3308 W: 64.9336 - National Park Service owns Hassel Island, but there are residential areas near the vessel that pre-date the park. - Small concrete building,	AVP
Unknown566	Medium	Grounded; 36' on shore	N: 18.3351 W: 64.9386	AWOIS

USVI - St. Thomas, Krum Bay

Krum Barges	Medium	Derelict; barge Multiple old barges all together in Krum Bay.	N: 18.3298 W: 64.9605 Industrial section of the bay.	AVP
Krum Tug	High	Derelict; tug Tug mixed in with barges in Krum Bay.	N: 18.3298 W: 64.9605 Industrial and marina area possibly on oil company property.	AVP
Unknown1958	Medium	Derelict;	S: 0 W: 0	

Abandoned Vessel Inventory

Vessel List :VI
April 08, 2004

Name	Priority	Description	Location	Primary Source
------	----------	-------------	----------	----------------

USVI - St. Thomas, Lindbergh B.

Unknown589	Low	Sunk; 18' fishing	N: 18.3351 W: 64.967	AWOIS
------------	-----	-------------------	----------------------	-------

USVI - St. Thomas, Muller Bay

Orca	Medium	Derelict; 41' sailboat Steel hulled sailboat grounded on the beach.	N: 18.3238 W: 64.8448 on beach, Muller Bay is part of Red Hook Bay - Public beach, small industrial area behind it. - Road behind beach.	AVP
------	--------	--	---	-----

USVI - St. Thomas, Red Hook

Vessup Bay 1	Medium	Derelict; in mangrove	S: 0 W: 0 in Vessup Bay, mangroves	NPS
--------------	--------	--------------------------	---------------------------------------	-----

Vessup Bay 2	Medium	Derelict;	S: 0 W: 0	NPS
--------------	--------	-----------	-----------	-----

USVI - St. Thomas, Saba I.

Munroe	High	Derelict 1999; 46' sailboat High end sailboat grounded after broken mooring & USCG rescue effort.	N: 18.31 W: 65 SW of St. Thomas - in a USVI wildlife sactuary	AVP
--------	------	--	---	-----

USVI - St. Thomas, St. Thomas Hbr

Abandoned Vessel Inventory

Vessel List :VI
April 08, 2004

Name	Priority	Description	Location	Primary Source
<i>USVI - St. Thomas, St. Thomas Hbr</i>				
French Kiss	Medium	Sunk; sailboat submerged in 10 meters	N: 18.3308 W: 64.9332	AWOIS
Quest	Medium	Sunk; sailboat in 6 meters; broken mast	N: 18.3308 W: 64.9331	AWOIS
Unknown572	Medium	Sunk; overturned in 4 meters	N: 18.3353 W: 64.9398	AWOIS
Unknown574	Medium	Sunk; sailboat in 5 meters; attached by cable to wreck Quest	N: 18.3306 W: 64.9329	AWOIS
Unknown580	Medium	Grounded; baring 1 foot	N: 18.3271 W: 64.9583	AWOIS
Unknown586	Medium	Grounded; sailboat upright in 2 meters; cream-colored	N: 18.3357 W: 64.94	AWOIS

Abandoned Vessel Inventory

Vessel List :VI
April 08, 2004

Name	Priority	Description	Location	Primary Source
------	----------	-------------	----------	----------------

USVI - St. Thomas, St. Thomas Hbr

Unknown590	Medium	Sunk; sailboat rocking in wave surge; close to deep- draft channel	N: 18.3252 W: 64.9286	AWOIS
------------	--------	--	-----------------------	-------

USVI - St. Thomas, Water I.

Party Ferry Boat	Medium	Derelict; 110' (recreational) party boat	N: 18.32 W: 64.94 on Revenge Bch, near Sprat Pt	individual
------------------	--------	---	--	------------